

DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED	APPROVED	DEO 9109 SHE	REV. A
DATE 98.08.24		ALUMINUM WELDING COUPON TESTING	SCALE
A 98.08.24		NEW ISSUE	

DART ENGINEERING ORDER

TO AMEND QSI OUT ISSUE Z

THE TYPE OF SKIDTUBE IN PRODUCTION CHANGES!

- 1. WELD (2) CROSSBOLT SPACERS INTO A SAMPLE PIECE OF SKIDTUBE EXTRUSION (26"LONG)
 PER THE APPLICABLE DWG (SEE SKETCH BELOW)
- 2. GRIND DOWN BOTH ENDS OF ONE CROSS BOLT SPACER UNTIL THE END OF THE SPACER IS USUBLE OR A WILD IS OBSERVED. MEASURE ACROSS THE CROSS BOLT SPACER TO CHECK FOR PENETRATION TO THE BOTTOM OF CHAMPER IN THE SKIDTUBE.
- 3. CUT LONGITUDINALLY THROUGH THE OTHER CROSSBOLT SPACER. CHECK FOR VOIDS OR PENETRATION TO THE BOTTOM OF THE CHAMPER IN THE SKIDTUBE EXTRUSION.
- 4. IDENTIFY THE TEST COUPON WITH THE WELDER'S NAME AND DATE THAT THE TEST WAS PERFORMED. FILL IN THE MIL-STD-1595A QUALIFICATION TEST RECORD. RETHIN COUPON.
- S. IF THE TEST IS UN SUCCESSFUL, REPORT IT TO THE MINUFACTURING MANAGER ... IMMEDIATELY FOR DISPOSITION. IF THE TEST IS SUCCESSFUL, CONTINUE WITH PRODUCTION.

